

Kinguard Collection process



Replas
27 Titan Drive,
Carrum Downs VIC 3201
Ph: (03) 9770 8390
Fax: (03) 9770 8490
Web: www.replas.com.au
Email: info@replas.com.au

Kinguard collection is a unique service and the service remains viable mainly due to the fact that the Hospital has **ensured that no contaminants are included in the sorted Kinguard.**

The hospital has taken on the responsibility to induct all staff that is involved with the Kinguard process. Frequent reviews of the process in place must be supported by the hospital management. **Each quarter all participants need to send via email documented facts about how** monthly reviews are being implemented which will ensure that the quality of the Kinguard is maintained.

All hospitals need to send a copy of their Kinguard quality sorting procedure to Replas prior to starting the program. The ability to ensure no contaminants are received in the waste is critical for the program to exist. Hospitals guidelines in relation to their Kinguard sorting process, should include, training, review process and the procedure.

The ability of each hospital to ensure that clear guidelines are in place is very important to the whole Victoria wide collection program. It will only take one metal contaminate to get into the system and this would mean costly (\$10,000 plus) repairs to the large granulator. Health issues like blood on Kinguard will not be tolerated. This would mean an end to the program.

Documented guidelines can be sent to Steven Pottinger email. steven@replas.com.au or to the mail address above.

Your attention to this important matter is appreciate and welcomed.